
INSTRUCTIONS DANGER !!!

Do Not Release Lever# 2 On the spring arm To Release Tension - Until Arm Is Being Held Securely On The Stand.





Optimetrics TS-700 Aluminum Tripod Stand w/ Counterbalanced Phoropter Arm.









Optimetrics TS-700 Aluminum Tripod Stand W/ Counterbalanced Phoropter Arm

INSTRUCTIONS

DANGER !!! Do Not Move Lever # 2


To Release Tension - Until Arm Is Being Held Securely On The Tripod.


1.- MOUNTING THE SPRING COUNTER BALANCED PHOROPTOR ARM:


- a) Open tripod legs
- b) Place filled water bag on ring as seen on the following picture



- c) Place the C/B Arm's Pin # 2b through the 90-degree mount # 4 and the Tripods center tube.
- d) With one hand pushing the C/B Arm down, turn adjustable lever # 2 to release tension.
- e) Move the 10" Phoroptor Arm # 3 out of storage position, to where the phoroptor can be attached.
- f) Slowly let C/B Arm move upwards.
- g) Now position the Arm so that it is over one of the tripod legs (this gives the tripod more stability)
- h) Tighten Knob #4b, also # 3c if you want the arm to remain in that position
- i) The Arm should be in its highest position
- j) The Phoroptor can now be placed on the Phoroptor Pin # 3a.







TRIPOD
1 Tripod

Optimetrics TS-700 Aluminum Tripod Stand W/ Counterbalanced Phoropter Arm.

